

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 4/16/2024 **Time:** 11:15 AM
Name of School Corporation: VIGO COUNTY SCHOOL CORPORATION **Corp ID:** 848030
Address of School Corporation: 3250 Maple Ave
City: Terre Haute **Zip:** 47804 **County Number:** 84
VIN: 4DRBWAAR5GB111826 **License Number:** 10025 **Bus Number:** 1548
Make of Body: IC Corporation **Year:** 2015 **Make of Chassis:** IC Corporation **Year:** 2016
Bus Type: D **Mileage:** 81311
Inspection Status: O **Inspected By:** Byron Goodman **PE:** 7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.