

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	4/17/2024	Time:	9:38 AM
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP	Corp ID:	131300		
Address of School Corporation:	5808 E Administration Rd				
City:	Marengo	Zip:	47140	County Number:	13
VIN:	1HA6GUB74NN012701	License Number:	25903	Bus Number:	45
Make of Body:	Thomas Built Buses, Inc.	Year:	2022	Make of Chassis:	Chevrolet
Bus Type:	A2	Mileage:	26331	Year:	2022
Inspection Status:	O	Inspected By:	Philip Lubbers	PE:	7703

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.