

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	4/19/2024	Time:	7:29 AM
Name of School Corporation:	RIVER FOREST COMM. SCHOOL CORP	Corp ID:	454590		
Address of School Corporation:	3250 Michigan St				
City:	Hobart	Zip:	46342	County Number:	45
VIN:	4UZABRDT4ECFT1665	License Number:	6758	Bus Number:	6
Make of Body:	Thomas Built Buses, Inc.	Year:	2013	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	60812		
Inspection Status:	O	Inspected By:	Nathan Sherer	PE:	7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
55-2-6	Steering box is loose on the frame

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.