## REPORT OF SCHOOL BUS INSPECTION

Type of 10:34 Time: Annual Date: 4/23/2024 Inspection: AM Name of School Corporation: WHITLEY CO. CONSOLIDATED SCHLS 928665 Corp ID: **Address of School Corporation:** 107 N Walnut St. County City: Columbia City Zip: 46725 92 Number: License VIN: 1T7YT4E2891117024 15779 Bus Number: 82 Number: Thomas Built Buses, Year: 2008 Thomas Built Buses, Year: Make of Make of Body: 2008 Chassis: Inc. **Bus Type:** D Mileage: 158845 Inspection Inspected R PE: Wes Rowlader 7427 Status: By:

## **Violations - Rejected**

<u>Inspection Code</u> <u>Description</u>

52-1-2 Any shock absorber is leaking fluid

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.