REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	4/24/2024	**Time:**	9:09 AM
Name of School Corporation:	SOUTH DEARBORN COMM. SCH. CORP				**Corp ID:**	151600
Address of School Corporation:	6109 Squire Place					
City:	Aurora	**Zip:**	47001		**County Number:**	15
VIN:	4UZABRDC78CZ10824		**License Number:**	B595R	**Bus Number:**	9
Make of Body:	Freightliner	**Year:** 2008	**Make of Chassis:**	Freightliner	**Year:**	2008
Bus Type:	A1		**Mileage:**	159478		
Inspection Status:	O	**Inspected By:**	Chris Clark		**PE:**	6665

Violations - Rejected

Inspection Code	Description
66-1-2	Any emergency device is in poor condition
57-1-2	Step-well area is weakened
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

Inspection Code	Description
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**