

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual **Date:** 4/24/2024 **Time:** 9:09 AM  
**Name of School Corporation:** SOUTH DEARBORN COMM. SCH. CORP **Corp ID:** 151600  
**Address of School Corporation:** 6109 Squire Place  
**City:** Aurora **Zip:** 47001 **County Number:** 15  
**VIN:** 4UZABRDC78CZ10824 **License Number:** B595R **Bus Number:** 9  
**Make of Body:** Freightliner **Year:** 2008 **Make of Chassis:** Freightliner **Year:** 2008  
**Bus Type:** A1 **Mileage:** 159478  
**Inspection Status:** O **Inspected By:** Chris Clark **PE:** 6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
66-1-2	Any emergency device is in poor condition
57-1-2	Step-well area is weakened
22-1-1	A dripping oil or fluid leak

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.