

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/24/2024	Time:	9:11 AM
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.	Corp ID:	525625		
Address of School Corporation:	PO Box 550				
City:	Converse	Zip:	46919	County Number:	52
VIN:	4UZABRFC6KCJZ5474	License Number:	1131	Bus Number:	14
Make of Body:	Thomas Built Buses, Inc.	Year:	2017	Make of Chassis:	Freightliner
Year:	2019	Year:	2019	Year:	2019
Bus Type:	C	Mileage:	88944	Year:	2019
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.