REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/29/2024	**Time:**	9:11 AM
Name of School Corporation:	HERITAGE HALL CHRISTIAN SCHOOL			**Corp ID:**	18-PS-HHC
Address of School Corporation:	6401 West River Road				
City:	Muncie	**Zip:**	47304	**County Number:**	18
VIN:	1HVBBPLP2NH447968	**License Number:**	B246AD	**Bus Number:**	5
Make of Body:	IC Corporation **Year:** 1992	**Make of Chassis:**	IC Corporation	**Year:**	1992
Bus Type:	C	**Mileage:**	248013		
Inspection Status:	O	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
46-1-1	Any seat is loose from the floor or seat rail
22-1-1	A dripping oil or fluid leak
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
30-1-1	There are any holes in the floor
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
29-1-4	Prohibited area line is missing or improper

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.