## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	4/29/2024	Time:	9:11 AM
Name of School Co	orporation:	HERI	TAGE HALL C	HRISTIAN SCHOO	L	Corp ID:	18-PS- HHC
Address of School	Corporation:		6401 West Riv	ver Road			
City:	Muncie		Zip:	47304		County Number:	18
VIN:	1HVBBPLP2N	H4479	968	License Number:	B246AD	Bus Number:	5
Make of Body:	IC Corporation	Year:	1992	Make of Chassis:	IC Corporation	Year:	1992
Bus Type:	С			Mileage:	248013		
Inspection Status:	0		Inspected By:	Steve Spallinger		PE:	6921

## **Violations - Rejected**

Inspection Code	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
46-1-1	Any seat is loose from the floor or seat rail
22-1-1	A dripping oil or fluid leak
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
30-1-1	There are any holes in the floor
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
29-1-4	Prohibited area line is missing or improper

## **Violations - Out of Service**

Inspection Code	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the
	bus to return home in a post crash inspection if bus is out of its district)).

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in

front of the windshield	The entrance door is behind the front wheels.
mont of the windsinera.	The childrice door is belined the front wheels.