

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	4/29/2024	<b>Time:</b>	9:47 AM
<b>Name of School Corporation:</b>	HERITAGE HALL CHRISTIAN SCHOOL	<b>Corp ID:</b>	18-PS-HHC		
<b>Address of School Corporation:</b>	6401 West River Road				
<b>City:</b>	Muncie	<b>Zip:</b>	47304	<b>County Number:</b>	18
<b>VIN:</b>	1HVBBPLP2NH447968	<b>License Number:</b>	B246AD	<b>Bus Number:</b>	5
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	1992	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	248013		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Steve Spallinger	<b>PE:</b>	6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
29-1-4	Prohibited area line is missing or improper
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
46-1-1	Any seat is loose from the floor or seat rail
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
22-1-1	A dripping oil or fluid leak
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
30-1-1	There are any holes in the floor

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**