## **REPORT OF SCHOOL BUS INSPECTION**

| Type of<br>Inspection:           | Annual                      |                       |                  | Date:               | 4/30/2024    | Time:             | 8:00<br>AM |
|----------------------------------|-----------------------------|-----------------------|------------------|---------------------|--------------|-------------------|------------|
| Name of School Corporation: M.S. |                             | .D. OF BOONE TOWNSHIP |                  | Corp ID:            | 646460       |                   |            |
| Address of School Corporation:   |                             |                       | 307 S Main St    |                     |              |                   |            |
| City:                            | Hebron                      |                       | Zip:             | 46341               |              | County<br>Number: | 64         |
| VIN:                             | 4UZABRDT6BCAT527            | 6                     |                  | License<br>Number:  | 72321        | Bus Number:       | 3          |
| Make of Body:                    | Thomas Built Buses,<br>Inc. | Year:                 | 2009             | Make of<br>Chassis: | Freightliner | Year:             | 2010       |
| Bus Type:                        | С                           |                       |                  | Mileage:            | 60841        |                   |            |
| Inspection Status                | :: 0                        |                       | Inspected<br>By: | Tim Grayson         |              | PE:               | 7558       |

## **Violations - Rejected**

| Inspection Code | <b>Description</b>           |
|-----------------|------------------------------|
| 34-1-1          | Any headlight is inoperative |

## Violations - Out of Service

Inspection CodeDescription69-2-1Wipers fail to function

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.