REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	ı	Date:	5/3/2024	Time:	10:10 AM
Name of School Address of School	Corporation: ool Corporation:	FIRST STUDENT xxx	- INDPLS		Corp ID:	4981
City:	Indianapolis	Zip:	46202		County Number:	49
VIN:	1T88Y9D25M117544	-	License Number:	B987R	Bus Number:	710
Make of Body:	Thomas Built Buses, Inc.	Year: 2020	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2020
Bus Type:	D		Mileage:	71398		
Inspection Status:	0	Inspected By:	Seth Davidson		PE:	8101

Violations - Rejected

Inspection Code	<u>Description</u>
64-1-4	Any front turn signal does not function properly
24-1-7	See Notes: Any defect inspector deems a violation not listed
34-1-5	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	<u>Description</u>
70-2-2	Any glass or glazing is cracked, chipped, clouded or distorted badly enough to prohibit a clear view from within the bus
51-2-1	The service door does not open or close properly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.