REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/6/2024	**Time:**	8:28 AM
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			**Corp ID:**	131300
Address of School Corporation:	5808 E Administration Rd				
City:	Marengo	**Zip:**	47140	**County Number:**	13
VIN:	1GBJG31U741225197	**License Number:**	6892	**Bus Number:**	40
Make of Body:	Mid Bus, Inc. **Year:** 2004	**Make of Chassis:**	Chevrolet	**Year:**	2004
Bus Type:	A2	**Mileage:**	246850		
Inspection Status:	R	**Inspected By:**	Philip Lubbers	**PE:**	7703

Violations - Rejected

Inspection Code	Description
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**