REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:5/6/2024Time:8:28 AMName of School Corporation:CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:1GBJG31U741225197License Number:6892Bus Number:40Make of Body:Mid Bus, Inc. Year:2004Make of Chassis:Chevrolet Year:2004

Bus Type: A2 Mileage: 246850

Inspection Status: R Inspected By: Philip Lubbers PE: 7703

Violations - Rejected

Inspection Code Description

22-1-1 A dripping oil or fluid leak

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.