REPORT OF SCHOOL BUS INSPECTION

Type of 9:11 Time: Annual Date: 5/6/2024 Inspection: AM Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300 **Address of School Corporation:** 5808 E Administration Rd County City: Marengo Zip: 47140 13 Number: License VIN: 4UZABRFC9RCUK4577 B307V Bus Number: 4 Number: Thomas Built Buses, Year: 2023 Thomas Built Buses, Year: Make of Make of Body: 2024 Chassis: Inc. **Bus Type:** С Mileage: 7794 Inspection Inspected R PE: 7703 Philip Lubbers Status: By:

Violations - Rejected

Inspection Code

Description

The seat belt cutter is not secured using a positive fastening method.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.