

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 5/8/2024 **Time:** 8:17 AM
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP **Corp ID:** 131300
Address of School Corporation: 5808 E Administration Rd
City: Marengo **Zip:** 47140 **County Number:** 13
VIN: 1GB3G2BGXC1107641 **License Number:** 10435 **Bus Number:** 87
Make of Body: Chevrolet **Year:** 2012 **Make of Chassis:** Chevrolet **Year:** 2012
Bus Type: A1 **Mileage:** 186874
Inspection Status: R **Inspected By:** Philip Lubbers **PE:** 7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.