

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 5/8/2024 Time: 8:17 AM  
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300  
Address of School Corporation: 5808 E Administration Rd  
City: Marengo Zip: 47140 County Number: 13  
VIN: 1GB3G2BGXC1107641 License Number: 10435 Bus Number: 87  
Make of Body: Chevrolet Year: 2012 Make of Chassis: Chevrolet Year: 2012  
Bus Type: A1 Mileage: 32002  
Inspection Status: O Inspected By: Philip Lubbers PE: 7703

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
17-1-1	Any dome light is inoperative
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

## Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.