## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 5/8/2024 Time: 8:35 AM Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:4UZAAXCS47CW45066License Number:24636Bus Number:9Make of Body:Freightliner Year:2007Make of Chassis:Freightliner Year:2007

Bus Type: C Mileage: 93815

Inspection Status: O Inspected By: Philip Lubbers PE: 7703

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

Inspection Code Description

7-2-1 There is no brake certification form the certification is expired or is not signed within the six-month requirement

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.