REPORT OF SCHOOL BUS INSPECTION

Type of 9:13 Annual Time: Date: 5/8/2024 Inspection: AM Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300 **Address of School Corporation:** 5808 E Administration Rd County City: Marengo Zip: 47140 13 Number: License VIN: 1BAKECPH19F260092 B579U Bus Number: 32 Number: Make of Blue Bird Blue Bird Year: 2008 Make of Body: Year: 2009 Corporation Chassis: Corporation **Bus Type:** С Mileage: 157463 Inspection Inspected R PE: 7703 Philip Lubbers Status: By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.