## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	: Annual		Date:	5/10/2024	Time:	9:55 AM
Name of School Corporation: TA		OR COMMUNI	TY SCHOOL CORP		Corp ID:	343460
Address of School	Corporation:	3750 E CR 300	) S			
City:	Kokomo	Zip:	46902		<b>County Number:</b>	34
VIN:	4DRBUC8N0FB6789	917	License Number:	8297	Bus Number:	20
Make of Body:	IC Corporation Year:	2014	Make of Chassis:	IC Corporation	Year:	2015
Bus Type:	С		Mileage:	102914		
Inspection Status:	R	Inspected By:	Randy McPike		PE:	7018

## **Violations - Rejected**

Inspection <u>Code</u>	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
64-1-4	Any front turn signal does not function properly
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement

## **Violations - Out of Service**

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.