

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/14/2024	Time:	11:53 AM
Name of School Corporation:	VIGO COUNTY SCHOOL CORPORATION	Corp ID:	848030		
Address of School Corporation:	3250 Maple Ave				
City:	Terre Haute	Zip:	47804	County Number:	84
VIN:	4DRBUC8N4LB829317	License Number:	23292	Bus Number:	1958
Make of Body:	IC Corporation	Year:	2019	Make of Chassis:	IC Corporation
Year:		Year:		Year:	2020
Bus Type:	C	Mileage:	39270	PE:	7008
Inspection Status:	O	Inspected By:	Byron Goodman		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
55-1-6	See Notes: Any defect inspector deems a violation not listed
7-1-5	See Notes: Any defect inspector deems a violation not listed
67-1-2	Rims are bent or loose
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
77-1-2	The communication system is mounted in a manner that would cause injuries in the event of a sudden stop
64-1-4	Any front turn signal does not function properly
56-1-1	Does not conform to original specifications
79-1-5	See Notes: Any defect inspector deems a violation not listed
33-1-2	The grill is missing

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat
34-2-1	Both lamps are inoperative on low beam
34-2-2	Both lamps are inoperative on high beam
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
31-2-1	Frame is deteriorated, cracked, broken or severely bent
65-2-5	LED lights have 50% or more of the pixels inoperable
15-2-1	Defroster is inoperative

70-2-1

Any glass or glazing is broken through or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.