REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	5/15/2024	**Time:**	10:21 AM
Name of School Corporation:		ELWOOD COMMUNITY SCHOOL CORP.				**Corp ID:**	485280
Address of School Corporation:		1306 N Anderson St					
City:	Elwood	**Zip:**	46036			**County Number:**	48
VIN:	4DRBUSKP9CB589444			**License Number:**	1582	**Bus Number:**	7
Make of Body:	IC Corporation	**Year:**	2011	**Make of Chassis:**	IC Corporation	**Year:**	2012
Bus Type:	C			**Mileage:**	75433		
Inspection Status:	R	**Inspected By:**	Brandon Steffee			**PE:**	8247

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.