

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	5/15/2024	Time:	1:33 PM
Name of School Corporation:	SOUTH DEARBORN COMM. SCH. CORP			Corp ID:	151600
Address of School Corporation:	6109 Squire Place				
City:	Aurora	Zip:	47001	County Number:	15
VIN:	1T88Y9D25R1214614	License Number:	26530	Bus Number:	5
Make of Body:	Thomas Built Buses, Inc.	Year:	2023	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	A1			Mileage:	14540
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
51-1-4	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.