## REPORT OF SCHOOL BUS INSPECTION

Type of 11:44 Time: Annual Date: 5/20/2024 Inspection: AM Name of School Corporation: FIRST STUDENT - INDPLS 4981 Corp ID: **Address of School Corporation:** XXX County City: Indianapolis Zip: 46202 49 Number: License VIN: 1BABLCSA3LF367025 **Bus Number:** 105 Number: Make of Blue Bird Blue Bird Year: 2019 Make of Body: Year: 2020 Corporation Chassis: Corporation Bus Type: D Mileage: 52654 Inspection Inspected 0 PE: Joel Flores 7415 Status: By:

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

57-1-5 Step-well light is missing or inoperative

## **Violations - Out of Service**

Inspection Code

Description

Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at

7-2-4 Arry brake line of flose is abraded (challed), cracked, buiging or lear other than a proper connection).

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.