REPORT OF SCHOOL BUS INSPECTION

Type of 10:28 Annual Date: 5/22/2024 **Time**: Inspection: AM Name of School Corporation: NORTH MIAMI COMMUNITY SCHOOLS 525620 Corp ID: **Address of School Corporation:** PO Box 218 County City: Denver Zip: 46926 52 Number: License VIN: 1GBJG31U171151196 32354 **Bus Number: A**3 Number: Make of Thomas Built Buses, Chevrolet Year: Year: 2007 Make of Body: 2007 Inc. Chassis: **Bus Type:** A2 Mileage: 135485 Inspected PE: **Inspection Status:** R Randy McPike 7018 By:

Violations - Rejected

Inspection Code	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
57-1-5	Step-well light is missing or inoperative
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.