

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	5/31/2024	<b>Time:</b>	10:03 AM
<b>Name of School Corporation:</b>	AUXILIO SERVICES (MUNCIE)	<b>Corp ID:</b>	251807		
<b>Address of School Corporation:</b>	11260 Cornell Park Dr Suite 700				
<b>City:</b>	Cincinnati	<b>Zip:</b>	45242	<b>County Number:</b>	18
<b>VIN:</b>	4DRBUC8N7JB043637	<b>License Number:</b>	B443U	<b>Bus Number:</b>	M31
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2017	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>			2017	<b>Year:</b>	2017
<b>Bus Type:</b>	C	<b>Mileage:</b>	62000		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Steve Spallinger	<b>PE:</b>	6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."
89-1-3	The strobe light is inoperative
46-1-1	Any seat is loose from the floor or seat rail

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**