

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	5/31/2024	<b>Time:</b>	10:17 AM
<b>Name of School Corporation:</b>	MUNCIE COMMUNITY SCHOOLS	<b>Corp ID:</b>	181970		
<b>Address of School Corporation:</b>	2501 N Oakwood				
<b>City:</b>	Muncie	<b>Zip:</b>	47304	<b>County Number:</b>	18
<b>VIN:</b>	1GBJC31U471202688	<b>License Number:</b>	73848	<b>Bus Number:</b>	3
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2007	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>		<b>Mileage:</b>	108323		
<b>Inspection Status:</b>	<input type="radio"/>	<b>Inspected By:</b>	Steve Spallinger	<b>PE:</b>	6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
11-1-7	See Notes: Any defect inspector deems a violation not listed
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed

### Bus Type Description