

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------|------------------------|------------------|-------------------------|-----------|
| Type of Inspection: | Annual | Date: | 5/31/2024 | Time: | 10:34 AM |
| Name of School Corporation: | MUNCIE COMMUNITY SCHOOLS | Corp ID: | 181970 | | |
| Address of School Corporation: | 2501 N Oakwood | | | | |
| City: | Muncie | Zip: | 47304 | County Number: | 18 |
| VIN: | 1GB6G2AG8A1148605 | License Number: | 83030 | Bus Number: | 7 |
| Make of Body: | Collins Bus Corporation | Year: | 2010 | Make of Chassis: | Chevrolet |
| Bus Type: | | Year: | 2010 | Mileage: | 34803 |
| Inspection Status: | <input type="radio"/> | Inspected By: | Steve Spallinger | PE: | 6921 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 75-1-5 | Fan is loosely attached or wobbles |
| 70-1-10 | If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle |
| 41-1-4 | There is debris in the bus. (needs cleaned/includes dirt) |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 8-2-1 | There is no brake certification, or the certification has expired or is not signed |

Bus Type Description