

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 5/31/2024 **Time:** 12:51 PM
Name of School Corporation: AUXILIO SERVICES (MUNCIE) **Corp ID:** 251807
Address of School Corporation: 11260 Cornell Park Dr Suite 700
City: Cincinnati **Zip:** 45242 **County Number:** 18
VIN: 1GB3GSBG2H1249232 **License Number:** B472S **Bus Number:** M35
Make of Body: Chevrolet **Year:** 2017 **Make of Chassis:** Chevrolet **Year:** 2017
Bus Type: A1 **Mileage:** 54610
Inspection Status: O **Inspected By:** Steve Spallinger **PE:** 6921

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.