

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 5/31/2024      **Time:** 12:51 PM  
**Name of School Corporation:** AUXILIO SERVICES (MUNCIE)      **Corp ID:** 251807  
**Address of School Corporation:** 11260 Cornell Park Dr Suite 700  
**City:** Cincinnati      **Zip:** 45242      **County Number:** 18  
**VIN:** 1GB3GSBG2H1249232      **License Number:** B472S      **Bus Number:** M35  
**Make of Body:** Chevrolet      **Year:** 2017      **Make of Chassis:** Chevrolet      **Year:** 2017  
**Bus Type:** A1      **Mileage:** 54610  
**Inspection Status:** O      **Inspected By:** Steve Spallinger      **PE:** 6921

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.