

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|---------------------------|-----------------|------------------|------------------|-----------|
| Type of Inspection: | Annual | Date: | 6/3/2024 | Time: | 9:33 AM |
| Name of School Corporation: | WES-DEL COMMUNITY SCHOOLS | Corp ID: | 181885 | | |
| Address of School Corporation: | 10290 N CR 600 W | | | | |
| City: | Gaston | Zip: | 47342 | County Number: | 18 |
| VIN: | 1HA6GUBG1LN005919 | License Number: | 24014 | Bus Number: | 13 |
| Make of Body: | Collins Bus Corporation | Year: | 2020 | Make of Chassis: | Chevrolet |
| Bus Type: | A1 | Mileage: | 34900 | Year: | 2020 |
| Inspection Status: | O | Inspected By: | Steve Spallinger | PE: | 6921 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 13-1-1 | Any clearance light is missing, cracked, faded, wrong color, or inoperative |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 64-2-1 | Any rear turn signal does not function properly |

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.