

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/11/2024	Time:	11:24 AM
Name of School Corporation:	RANDOLPH SOUTHERN SCHOOL CORP.			Corp ID:	686805
Address of School Corporation:	One Rebel Dr				
City:	Lynn	Zip:	47355	County Number:	68
VIN:	4UZABRDU3ECFT7322	License Number:	6810	Bus Number:	2
Make of Body:	Thomas Built Buses, Inc.	Year:	2013	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C			Mileage:	109454
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
67-1-1	Rims and wheels are painted any other color than black or gray. (Aluminum wheels may be of natural color) (MFSAB's are permitted to have factory wheels)
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
25-1-1	Mirror or mirror backs that are loose or improperly mounted
60-1-1	Sun visor is missing, cracked or broken
49-1-4	Any reflector is missing, cracked, faded, or the wrong color.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
32-2-1	There is fuel leaking from any point on in the fuel system
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.