## REPORT OF SCHOOL BUS INSPECTION

Type of 11:43 Annual Time: Date: 6/11/2024 Inspection: AM Name of School Corporation: RANDOLPH SOUTHERN SCHOOL CORP. Corp ID: 686805 **Address of School Corporation:** One Rebel Dr County City: Lynn Zip: 47355 68 Number: License VIN: 4UZABRFD2LCLH7940 22636 Bus Number: 1 Number: Thomas Built Buses, Year: 2018 Thomas Built Buses, Year: Make of Make of Body: 2019 Inc. Chassis: Inc. **Bus Type:** С Mileage: 53762 Inspection Inspected R Steve Spallinger PE: 6921 Status: By:

# Violations - Rejected

<b>Inspection Code</b>	<u>Description</u>
60-1-1	Sun visor is missing, cracked or broken
46-1-3	Any required padding is missing
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

#### **Violations - Out of Service**

## **Inspection Code Description**

### **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.