REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	6/13/2024	Time:	10:56 AM
Name of School Corpo	ration: RICH	MOND COMMU	JNITY SCHOOL CC	RP	Corp ID:	898385
Address of School Cor	poration:	3175 north sali	sbury road			
City:	richmond	Zip:	47374		County Number:	89
VIN:	1FDFE4FP	ADA22883	License Number:	84262	Bus Number:	76
Make of Body:	Ford Year:	2009	Make of Chassis:	Ford	Year:	2009
Bus Type:			Mileage:	17995		
Inspection Status:	А	Inspected By:	Brandon Steffee		PE:	8247

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description