

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 6/18/2024	<b>Time:</b> 9:04 AM
<b>Name of School Corporation:</b> JOHN GLENN SCHOOL CORPORATION	<b>Corp ID:</b> 717150	
<b>Address of School Corporation:</b> 101 John Glen Dr		
<b>City:</b> Walkerton	<b>Zip:</b> 46574	<b>County Number:</b> 71
<b>VIN:</b> 4DRBUAAN2CB628885	<b>License Number:</b> 2034	<b>Bus Number:</b> 4
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2011	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2012	<b>Mileage:</b> 132534	<b>PE:</b> 8022
<b>Bus Type:</b> C	<b>Inspected By:</b> Travis Harrold	
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
26-1-5	Not readily accessible to the driver
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
41-2-1	Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students)

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.