

# REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual **Date:** 6/27/2024 **Time:** 1:41 PM  
**Name of School Corporation:** CARROLL CONS. SCHOOL CORP. **Corp ID:** 80750  
**Address of School Corporation:** 2 S 3rd St.  
**City:** Flora **Zip:** 46929 **County Number:** 8  
**VIN:** 1GB3G2BL3E1174467 **License Number:** 26781 **Bus Number:** 5sb  
**Make of Body:** Starcraft **Year:** 2014 **Make of Chassis:** Starcraft **Year:** 2014  
**Bus Type:** **Mileage:** 90784  
**Inspection Status:** R **Inspected By:** Nate King **PE:** 7421

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

## Bus Type Description