#### REPORT OF SCHOOL BUS INSPECTION

Type of Re-Inspection:

Name of School Corporation:

NORTH ADAMS COMM. SCHOOLS

Time:

11:27
AM

Corp ID:

10025

**Address of School Corporation:** 

City: Zip: County Number:

VIN: 1BABNCSA3MF375654 License 30781 Bus Number: 11

Make of Body: Blue Bird Corporation Year: 2020 Make of Chassis: Blue Bird Corporation Year: 2021

Bus Type: D Mileage: 63837

Inspection O Inspected Steve Spallinger PE: 6921

Status: By:

### Violations - Rejected

# <u>Inspection Code</u> <u>Description</u>

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

#### **Violations - Out of Service**

<u>Inspection Code</u> <u>Description</u>

50-2-1 There is no seat belt cutter in the vehicle

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.