REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	7/10/2024	**Time:**	11:27 AM
Name of School Corporation:	NORTH ADAMS COMM. SCHOOLS			**Corp ID:**	10025
Address of School Corporation:					
City:		**Zip:**		**County Number:**	1
VIN:	1BABNCSA3MF375654	**License Number:**	30781	**Bus Number:**	11
Make of Body:	Blue Bird Corporation **Year:** 2020	**Make of Chassis:**	Blue Bird Corporation	**Year:**	2021
Bus Type:	D	**Mileage:**	63837		
Inspection Status:	O	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code	Description
50-2-1	There is no seat belt cutter in the vehicle

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.