

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/10/2024	Time:	11:27 AM
Name of School Corporation:	NORTH ADAMS COMM. SCHOOLS			Corp ID:	10025
Address of School Corporation:					
City:		Zip:		County Number:	1
VIN:	1BABNCSA3MF375654	License Number:	30781	Bus Number:	11
Make of Body:	Blue Bird Corporation	Year:	2020	Make of Chassis:	Blue Bird Corporation
Bus Type:	D	Mileage:	63837	Year:	2021
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
50-2-1	There is no seat belt cutter in the vehicle

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.