

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 7/10/2024 **Time:** 11:44 AM
Name of School Corporation: NORTHEAST SCHOOL CORPORATION **Corp ID:** 777645
Address of School Corporation: PO Box 493
City: Hymera **Zip:** 47855 **County Number:** 77
VIN: 4DRBWAAR9EB775155 **License Number:** 6212 **Bus Number:** 24
Make of Body: IC Corporation **Year:** 2013 **Make of Chassis:** IC Corporation **Year:** 2014
Bus Type: D **Mileage:** 87103
Inspection Status: O **Inspected By:** Byron Goodman **PE:** 7008

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
64-2-1	Any rear turn signal does not function properly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.