REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 7/11/2024 Time: 10:31 AM

Name of School Corporation: SCHOOL CITY OF HOBART SERVICE CTR Corp ID: 454730

Address of School Corporation: 200 S Hobart Rd

City: Hobart Zip: 46342 County Number: 45
VIN: 4DRBUAAN0EB765617 License Number: 6700 Bus Number: 10

Make of Body: Year: 2013 Make of Chassis: IC Corporation Year: 2014

Bus Type: C Mileage: 114785

Inspection Status: O Inspected By: Tim Grayson PE: 7558

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

7-2-4 Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.