REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	7/11/2024	**Time:**	10:41 AM
Name of School Corporation:		SCHOOL CITY OF HOBART SERVICE CTR				**Corp ID:**	454730
Address of School Corporation:		200 S Hobart Rd					
City:	Hobart	**Zip:**	46342			**County Number:**	45
VIN:	4DRBUC8N9GB210590			**License Number:**	10331	**Bus Number:**	19
Make of Body:	IC Corporation	**Year:**	2015	**Make of Chassis:**	IC Corporation	**Year:**	2016
Bus Type:	C			**Mileage:**	90810		
Inspection Status:	R	**Inspected By:**	Tim Grayson			**PE:**	7558

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.