

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 7/22/2024	<b>Time:</b> 11:47 AM
<b>Name of School Corporation:</b>	BROWNSBURG COMM. SCHOOL CORP.	<b>Corp ID:</b> 323305
<b>Address of School Corporation:</b>	310 Stadium Drive	
<b>City:</b> Brownsburg	<b>Zip:</b> 46112	<b>County Number:</b> 32
<b>VIN:</b> 4UZABRFC4LCLL7144	<b>License Number:</b> 23239	<b>Bus Number:</b> 37
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2018	<b>Make of Chassis:</b> Freightliner
<b>Year:</b> 2020	<b>Mileage:</b> 63671	<b>PE:</b> 7415
<b>Bus Type:</b> C	<b>Inspected By:</b> Joel Flores	
<b>Inspection Status:</b> O		

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely

#### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**