

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	7/25/2024	Time:	11:10 AM		
Name of School Corporation:	KOKOMO SCHOOL CORPORATION			Corp ID:	343500		
Address of School Corporation:	620 W Deffenbaugh						
City:	Kokomo	Zip:	46901	County Number:	34		
VIN:	1GB3GSB70N1177068		License Number:	25637	Bus Number:	124	
Make of Body:	Thomas Built Buses, Inc.	Year:	2022	Make of Chassis:	Chevrolet	Year:	2022
Bus Type:	A2			Mileage:	31962		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
49-1-4	Any reflector is missing, cracked, faded, or the wrong color.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
3-1-7	Battery compartment door is not securely fastened.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
51-1-4	See Notes: Any defect inspector deems a violation not listed
51-1-1	Any door seals are missing, damaged, or torn
57-1-2	Step-well area is weakened
57-1-8	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.