

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 7/29/2024	<b>Time:</b> 9:49 AM
<b>Name of School Corporation:</b> FIRST STUDENT - INDPLS	<b>Corp ID:</b> 4981	
<b>Address of School Corporation:</b> xxx		
<b>City:</b> Indianapolis	<b>Zip:</b> 46202	<b>County Number:</b> 49
<b>VIN:</b> 4DRBUC8N7KB056678	<b>License Number:</b> B527T	<b>Bus Number:</b> 482
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2018	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2019	<b>Mileage:</b> 82670	<b>PE:</b> 8184
<b>Bus Type:</b> C	<b>Inspected By:</b> Jeff Stone	
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-5	There are holes, slots or brackets on the rear bumper which may be used as a step
73-1-1	The air horn is not properly mounted
2-1-5	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-9	There is any defect not in compliance with the minimum school bus brake inspection standards
7-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**