

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 8/12/2024	Time: 8:47 AM
Name of School Corporation: AVON COMMUNITY SCHOOLS	Corp ID: 323315	
Address of School Corporation: 7203 E HWY 36		
City: Avon	Zip: 46123	County Number: 32
VIN: 4DRBWAAR59A070767	License Number: 31473	Bus Number: 56
Make of Body: IC Corporation	Year: 2008	Make of Chassis: IC Corporation
Year: 2009		
Bus Type: D	Mileage: 140578	
Inspection Status: R	Inspected By: Jeff Stone	PE: 8184

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-5	There are holes, slots or brackets on the rear bumper which may be used as a step
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.