

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Spot Checks	Date: 8/14/2024	Time: 9:51 AM	
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP	Corp ID: 131300		
Address of School Corporation: 5808 E Administration Rd			
City: Marengo	Zip: 47140	County Number: 13	
VIN: 4DRBUSKPXEB405437	License Number: 7194	Bus Number: 55	
Make of Body: IC Corporation	Year: 2014	Make of Chassis: IC Corporation	Year: 2014
Bus Type: C	Mileage: 146496		
Inspection Status: R	Inspected By: Philip Lubbers	PE: 7703	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.