

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|-----------|-------------------------|--------------|
| Type of Inspection: | Semi-Annual | Date: | 8/22/2024 | Time: | 8:03 AM |
| Name of School Corporation: | SCOTT COUNTY SCHOOL DISTRICT 2 | | | Corp ID: | 727255 |
| Address of School Corporation: | 375 E McClain | | | | |
| City: | Scottsburg | Zip: | 47170 | County Number: | 72 |
| VIN: | 1T88S4E1891107616 | License Number: | 31179 | Bus Number: | V8 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2007 | Make of Chassis: | Freightliner |
| Year: | | Year: | | Year: | 2009 |
| Bus Type: | D | Mileage: | 150737 | | |
| Inspection Status: | O | Inspected By: | Troy Boyd | PE: | 5171 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 23-1-3 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |
| 23-1-2 | Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted) |
| 70-1-10 | If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 8-2-1 | There is no brake certification, or the certification has expired or is not signed |
| 70-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.