REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	8/23/2024	**Time:**	12:42 PM
Name of School Corporation:	CLARKSVILLE COMM. SCHOOL CORP.			**Corp ID:**	101000
Address of School Corporation:	200 Ettels Lane				
City:	Clarksville	**Zip:**	47130	**County Number:**	10
VIN:	4DRBUC8P3LB173192	**License Number:**	23558	**Bus Number:**	10
Make of Body:	IC Corporation **Year:** 2019	**Make of Chassis:**	IC Corporation	**Year:**	2020
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Troy Boyd	**PE:**	5171

Violations - Rejected

Inspection Code	Description
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
2-1-3	Any back-up light lens is cracked, broken, faded or missing
62-1-1	Any lens is cracked, missing, faded or of the wrong color
62-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.