

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/23/2024	Time:	12:42 PM		
Name of School Corporation:	CLARKSVILLE COMM. SCHOOL CORP.			Corp ID:	101000		
Address of School Corporation:	200 Ettels Lane						
City:	Clarksville	Zip:	47130	County Number:	10		
VIN:	4DRBUC8P3LB173192		License Number:	23558	Bus Number:	10	
Make of Body:	IC Corporation	Year:	2019	Make of Chassis:	IC Corporation	Year:	2020
Bus Type:	C			Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Troy Boyd	PE:	5171		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
2-1-3	Any back-up light lens is cracked, broken, faded or missing
62-1-1	Any lens is cracked, missing, faded or of the wrong color
62-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.